Illinois Commerce Commission Pipeline Safety

Pipeline Safety Report

Inspection #: 2015-P-00417

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513				
Exit Meeting Contact: John Sigler	Total Man Days: 2				
Pipeline Safety Representative(s): Donald Hankins					
Company Representative to Receive Report: Michael Fuller	Emailed Date:				
Company Representative's Email Address: mfuller2@ameren.com	01/13/2016				

Inspection Summary

Inspection Type	Location	ICC Analyst	Inspection Unit(s)	Man Day(s)	Inspection Date(s)	Contact(s)
Design Testing and Construction	Lincoln	Donald Hankins	Lincoln		11/10/2015, 11/12/2015	John Sigler

Statement of Activities

On November 10 and 12, 2015, a construction audit was conducted at Ameren Illinois, in Lincoln, Illinois, to determine compliance with applicable IL Adm. Codes and the Code of Federal Regulations adopted via IL Adm. Part 590.

On November 10, 2015, an Ameren Illinois crew was installing a new plastic service line into 409 South Gillette Street in Elkhart, Illinois. The new service line was 1/2 inch Driscoplex pipe. The service line was 98 feet long, and air tested to 102 pounds for 20 minutes, with no leaks being found.

On November 12, 2015, an Ameren Illinois crew was installing a new plastic service line into 606 Prairie Meadow Drive in Heyworth, Illinois. The 1/2 inch service line was installed with tracer wire being included in the ditch line, and was air tested to 100 pounds for 32 minutes with no leaks being found.

Exit Statement

INSPECTION FINDINGS

Design Testing and Construction

Issues(s) Found:

[NO ISSUES FOUND]

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

[NO NOPVS FOUND]

PAST INSPECTION FINDINGS

Issue(s) Corrected:

Illinois Commerce Commission Pipeline Safety Pipeline Safety Report

Inspection #: 2015-P-00417

[NO ISSUES CORRECTED]

Notice Of Amendment(s) Corrected:

[NO NOAS CORRECTED]

Notice of Violations(s) Corrected:

[NO NOPVS CORRECTED]